



ATxmega128/64/32/16A4U

ATxmega128/64/32/16A4U Silicon Errata and Data Sheet Clarification

Introduction

The ATxmega128/64/32/16A4U devices you have received conform functionally to the current device data sheet (<http://www.microchip.com/DS40002166>), except for the anomalies described in this document. The errata described in this document will likely be addressed in future revisions of the ATxmega128/64/32/16A4U devices.

Note:

- This document summarizes all the silicon errata issues from all revisions of silicon, previous as well as current.

Table of Contents

Introduction.....	1
1. Silicon Issue Summary.....	3
2. Silicon Errata Issues.....	4
2.1. Errata Details.....	4
2.2. ADC - Analog to Digital Converter.....	4
2.3. CRC - Cyclic Redundancy Check.....	4
2.4. AWeX - Advanced Waveform eXtension.....	5
2.5. Hi-Res - High-Resolution Extension.....	6
3. Data Sheet Clarifications.....	7
3.1. None.....	7
4. Document Revision History.....	8
4.1. Revision History.....	8
The Microchip Website.....	9
Product Change Notification Service.....	9
Customer Support.....	9
Microchip Devices Code Protection Feature.....	9
Legal Notice.....	9
Trademarks.....	10
Quality Management System.....	10
Worldwide Sales and Service.....	11

1. Silicon Issue Summary

Legend

- Erratum is not applicable.
- X Erratum is applicable.
- * This silicon revision was never released to production.

Peripheral	Short Description	Valid for Silicon Revision							
		ATxmega16A4U		ATxmega32A4U		ATxmega64A4U			ATxmega128A4U
		Rev. A-D	Rev. E	Rev. A-D	Rev. E	Rev. A-B	Rev. C	Rev. D	Rev. A
ADC	ADC May Have Missing Codes in Single Ended Unsigned Mode at Low Temp and Low V _{CC}	*	X	*	X	*	X	X	X
CRC	CRC Fails for Range CRC When End Address is the Last Word Address of a Flash Section	*	X	*	X	*	X	X	-
AWeX	AWeX Fault Protection Restore is Not Done Correctly in Pattern Generation Mode	*	X	*	X	*	X	-	-
Hi-Res	Hi-Res Extension Does Not Work for TC0/1 CCB and CCD	*	X	X	X	*	X	X	X

2. Silicon Errata Issues

2.1 Errata Details

- Erratum is not applicable.
- X** Erratum is applicable.
- * This silicon revision was never released to production.

2.2 ADC - Analog to Digital Converter

2.2.1 ADC May Have Missing Codes in Single Ended (SE) Unsigned Mode at Low Temp. and Low V_{CC}

The ADC may have missing codes in SE unsigned mode below 0°C when V_{CC} is below 1.8V.

Workaround

Use the ADC in SE signed mode.

Affected Silicon Revisions

ATxmega16A4U		
Rev. A - D	Rev. E	
*	X	

ATxmega32A4U	
Rev. A - D	Rev. E
*	X

ATxmega64A4U		
Rev. A-B	Rev. C	Rev. D
*	X	X

ATxmega128A4U	
Rev. A	
X	

2.3 CRC - Cyclic Redundancy Check

2.3.1 CRC Fails for Range CRC When End Address is the Last Word Address of a Flash Section

If the boot read lock is enabled, the range CRC cannot end on the last address of the application section. If the application table read lock is enabled, the range CRC cannot end on the last address before the application table.

Workaround

Ensure that the end address used in Range CRC does not end at the last address before a section with read lock is enabled. Instead, use the dedicated CRC commands for complete application sections.

Affected Silicon Revisions

ATxmega16A4U		
Rev. A - D	Rev. E	
*	X	

ATxmega32A4U	
Rev. A - D	Rev. E
*	X

ATxmega64A4U		
Rev. A-B	Rev. C	Rev. D
*	X	X

ATxmega128A4U	
Rev. A	
-	

2.4 AWeX - Advanced Waveform eXtension

2.4.1 AWeX Fault Protection Restore is Not Done Correctly in Pattern Generation Mode

When a fault is detected, the OUTOVEN register is cleared, and when the fault condition is cleared, OUTOVEN is restored according to the corresponding enabled DTI channels. For Common Waveform Channel Mode (CWCM), this has no effect as the OUTOVEN is correct after restoring from fault. For Pattern Generation Mode (PGM), OUTOVEN should instead have been restored according to the DTLSEBUF register.

Workaround

For CWCM, no workaround is required.

For PGM in latched mode, disable the DTI channels before returning from the fault condition. Then, set the correct OUTOVEN value and enable the DTI channels, before the direction (DIR) register is written to enable the correct outputs again.

Affected Silicon Revisions

ATxmega16A4U		
Rev. A - D	Rev. E	
*	X	

ATxmega32A4U	
Rev. A - D	Rev. E
*	X

ATxmega64A4U		
Rev. A-B	Rev. C	Rev. D
*	X	-

ATxmega128A4U	
Rev. A	-

2.5 Hi-Res - High-Resolution Extension

2.5.1 Hi-Res Extension Does Not Work for TC0/1 CCB and CCD

Enabling TC0/1 CCB or CCD with the Hi-res extension will cause incorrect values on belonging channel output in any of the waveform generation modes.

Workaround

None.

Affected Silicon Revisions

ATxmega16A4U	
Rev. A - D	Rev. E
*	X

ATxmega32A4U	
Rev. A - D	Rev. E
*	X

ATxmega64A4U		
Rev. A-B	Rev. C	Rev. D
*	X	X

ATxmega128A4U	
Rev. A	X

3. Data Sheet Clarifications

The following typographic corrections and clarifications are to be noted for the latest version of the device data sheet (<http://microchip.com/DS40002166>).

Note: Corrections are shown in **bold**. Where possible, the original bold text formatting has been removed for clarity.

3.1 None

There are no known data sheet clarifications as of this publication date.

4. Document Revision History

Note: The data sheet clarification document revision is independent of the die revision and the device variant (last letter of the ordering number).

4.1 Revision History

Doc. Rev.	Date	Comments
A	04/2020	Initial release of this document. <ul style="list-style-type: none">• Content moved from the data sheet and restructured to the new document template• Updated the die revision list to reflect die revisions in production• Added silicon issue <i>Hi-Res Extension Does Not Work for TC0/1 CCB and CCD</i>

The Microchip Website

Microchip provides online support via our website at <http://www.microchip.com/>. This website is used to make files and information easily available to customers. Some of the content available includes:

- **Product Support** – Data sheets and errata, application notes and sample programs, design resources, user's guides and hardware support documents, latest software releases and archived software
- **General Technical Support** – Frequently Asked Questions (FAQs), technical support requests, online discussion groups, Microchip design partner program member listing
- **Business of Microchip** – Product selector and ordering guides, latest Microchip press releases, listing of seminars and events, listings of Microchip sales offices, distributors and factory representatives

Product Change Notification Service

Microchip's product change notification service helps keep customers current on Microchip products. Subscribers will receive email notification whenever there are changes, updates, revisions or errata related to a specified product family or development tool of interest.

To register, go to <http://www.microchip.com/pcn> and follow the registration instructions.

Customer Support

Users of Microchip products can receive assistance through several channels:

- Distributor or Representative
- Local Sales Office
- Embedded Solutions Engineer (ESE)
- Technical Support

Customers should contact their distributor, representative or ESE for support. Local sales offices are also available to help customers. A listing of sales offices and locations is included in this document.

Technical support is available through the website at: <http://www.microchip.com/support>

Microchip Devices Code Protection Feature

Note the following details of the code protection feature on Microchip devices:

- Microchip products meet the specification contained in their particular Microchip Data Sheet.
- Microchip believes that its family of products is one of the most secure families of its kind on the market today, when used in the intended manner and under normal conditions.
- There are dishonest and possibly illegal methods used to breach the code protection feature. All of these methods, to our knowledge, require using the Microchip products in a manner outside the operating specifications contained in Microchip's Data Sheets. Most likely, the person doing so is engaged in theft of intellectual property.
- Microchip is willing to work with the customer who is concerned about the integrity of their code.
- Neither Microchip nor any other semiconductor manufacturer can guarantee the security of their code. Code protection does not mean that we are guaranteeing the product as "unbreakable."

Code protection is constantly evolving. We at Microchip are committed to continuously improving the code protection features of our products. Attempts to break Microchip's code protection feature may be a violation of the Digital Millennium Copyright Act. If such acts allow unauthorized access to your software or other copyrighted work, you may have a right to sue for relief under that Act.

Legal Notice

Information contained in this publication regarding device applications and the like is provided only for your convenience and may be superseded by updates. It is your responsibility to ensure that your application meets with

your specifications. MICROCHIP MAKES NO REPRESENTATIONS OR WARRANTIES OF ANY KIND WHETHER EXPRESS OR IMPLIED, WRITTEN OR ORAL, STATUTORY OR OTHERWISE, RELATED TO THE INFORMATION, INCLUDING BUT NOT LIMITED TO ITS CONDITION, QUALITY, PERFORMANCE, MERCHANTABILITY OR FITNESS FOR PURPOSE. Microchip disclaims all liability arising from this information and its use. Use of Microchip devices in life support and/or safety applications is entirely at the buyer's risk, and the buyer agrees to defend, indemnify and hold harmless Microchip from any and all damages, claims, suits, or expenses resulting from such use. No licenses are conveyed, implicitly or otherwise, under any Microchip intellectual property rights unless otherwise stated.

Trademarks

The Microchip name and logo, the Microchip logo, Adaptec, AnyRate, AVR, AVR logo, AVR Freaks, BesTime, BitCloud, chipKIT, chipKIT logo, CryptoMemory, CryptoRF, dsPIC, FlashFlex, flexPWR, HELDO, IGLOO, JukeBlox, KeeLoq, Kleer, LANCheck, LinkMD, maXStylus, maXTouch, MediaLB, megaAVR, Microsemi, Microsemi logo, MOST, MOST logo, MPLAB, OptoLyzer, PackeTime, PIC, picoPower, PICSTART, PIC32 logo, PolarFire, Prochip Designer, QTouch, SAM-BA, SenGenuity, SpyNIC, SST, SST Logo, SuperFlash, Symmetricom, SyncServer, Tachyon, TempTrackr, TimeSource, tinyAVR, UNI/O, Vectron, and XMEGA are registered trademarks of Microchip Technology Incorporated in the U.S.A. and other countries.

APT, ClockWorks, The Embedded Control Solutions Company, EtherSynch, FlashTec, Hyper Speed Control, HyperLight Load, IntelliMOS, Libero, motorBench, mTouch, Powermite 3, Precision Edge, ProASIC, ProASIC Plus, ProASIC Plus logo, Quiet-Wire, SmartFusion, SyncWorld, Temux, TimeCesium, TimeHub, TimePictra, TimeProvider, Vite, WinPath, and ZL are registered trademarks of Microchip Technology Incorporated in the U.S.A.

Adjacent Key Suppression, AKS, Analog-for-the-Digital Age, Any Capacitor, AnyIn, AnyOut, BlueSky, BodyCom, CodeGuard, CryptoAuthentication, CryptoAutomotive, CryptoCompanion, CryptoController, dsPICDEM, dsPICDEM.net, Dynamic Average Matching, DAM, ECAN, EtherGREEN, In-Circuit Serial Programming, ICSP, INICnet, Inter-Chip Connectivity, JitterBlocker, KleerNet, KleerNet logo, memBrain, Mindi, MiWi, MPASM, MPF, MPLAB Certified logo, MPLIB, MPLINK, MultiTRAK, NetDetach, Omniscient Code Generation, PICDEM, PICDEM.net, PICkit, PICtail, PowerSmart, PureSilicon, QMatrix, REAL ICE, Ripple Blocker, SAM-ICE, Serial Quad I/O, SMART-I.S., SQI, SuperSwitcher, SuperSwitcher II, Total Endurance, TSHARC, USBCheck, VariSense, ViewSpan, WiperLock, Wireless DNA, and ZENA are trademarks of Microchip Technology Incorporated in the U.S.A. and other countries.

SQTP is a service mark of Microchip Technology Incorporated in the U.S.A.

The Adaptec logo, Frequency on Demand, Silicon Storage Technology, and Symmcom are registered trademarks of Microchip Technology Inc. in other countries.

GestIC is a registered trademark of Microchip Technology Germany II GmbH & Co. KG, a subsidiary of Microchip Technology Inc., in other countries.

All other trademarks mentioned herein are property of their respective companies.

© 2020, Microchip Technology Incorporated, Printed in the U.S.A., All Rights Reserved.

ISBN: 978-1-5224-5406-9

Quality Management System

For information regarding Microchip's Quality Management Systems, please visit <http://www.microchip.com/quality>.

Worldwide Sales and Service

AMERICAS	ASIA/PACIFIC	ASIA/PACIFIC	EUROPE
<p>Corporate Office 2355 West Chandler Blvd. Chandler, AZ 85224-6199 Tel: 480-792-7200 Tel: 480-792-7277 Technical Support: http://www.microchip.com/support Web Address: http://www.microchip.com</p> <p>Atlanta Duluth, GA Tel: 678-957-9614 Fax: 678-957-1455</p> <p>Austin, TX Tel: 512-257-3370</p> <p>Boston Westborough, MA Tel: 774-760-0087 Fax: 774-760-0088</p> <p>Chicago Itasca, IL Tel: 630-285-0071 Fax: 630-285-0075</p> <p>Dallas Addison, TX Tel: 972-818-7423 Fax: 972-818-2924</p> <p>Detroit Novi, MI Tel: 248-848-4000</p> <p>Houston, TX Tel: 281-894-5983</p> <p>Indianapolis Noblesville, IN Tel: 317-773-8323 Fax: 317-773-5453 Tel: 317-536-2380</p> <p>Los Angeles Mission Viejo, CA Tel: 949-462-9523 Fax: 949-462-9608 Tel: 951-273-7800</p> <p>Raleigh, NC Tel: 919-844-7510</p> <p>New York, NY Tel: 631-435-6000</p> <p>San Jose, CA Tel: 408-735-9110 Tel: 408-436-4270</p> <p>Canada - Toronto Tel: 905-695-1980 Fax: 905-695-2078</p>	<p>Australia - Sydney Tel: 61-2-9868-6733</p> <p>China - Beijing Tel: 86-10-8569-7000</p> <p>China - Chengdu Tel: 86-28-8665-5511</p> <p>China - Chongqing Tel: 86-23-8980-9588</p> <p>China - Dongguan Tel: 86-769-8702-9880</p> <p>China - Guangzhou Tel: 86-20-8755-8029</p> <p>China - Hangzhou Tel: 86-571-8792-8115</p> <p>China - Hong Kong SAR Tel: 852-2943-5100</p> <p>China - Nanjing Tel: 86-25-8473-2460</p> <p>China - Qingdao Tel: 86-532-8502-7355</p> <p>China - Shanghai Tel: 86-21-3326-8000</p> <p>China - Shenyang Tel: 86-24-2334-2829</p> <p>China - Shenzhen Tel: 86-755-8864-2200</p> <p>China - Suzhou Tel: 86-186-6233-1526</p> <p>China - Wuhan Tel: 86-27-5980-5300</p> <p>China - Xian Tel: 86-29-8833-7252</p> <p>China - Xiamen Tel: 86-592-2388138</p> <p>China - Zhuhai Tel: 86-756-3210040</p>	<p>India - Bangalore Tel: 91-80-3090-4444</p> <p>India - New Delhi Tel: 91-11-4160-8631</p> <p>India - Pune Tel: 91-20-4121-0141</p> <p>Japan - Osaka Tel: 81-6-6152-7160</p> <p>Japan - Tokyo Tel: 81-3-6880-3770</p> <p>Korea - Daegu Tel: 82-53-744-4301</p> <p>Korea - Seoul Tel: 82-2-554-7200</p> <p>Malaysia - Kuala Lumpur Tel: 60-3-7651-7906</p> <p>Malaysia - Penang Tel: 60-4-227-8870</p> <p>Philippines - Manila Tel: 63-2-634-9065</p> <p>Singapore Tel: 65-6334-8870</p> <p>Taiwan - Hsin Chu Tel: 886-3-577-8366</p> <p>Taiwan - Kaohsiung Tel: 886-7-213-7830</p> <p>Taiwan - Taipei Tel: 886-2-2508-8600</p> <p>Thailand - Bangkok Tel: 66-2-694-1351</p> <p>Vietnam - Ho Chi Minh Tel: 84-28-5448-2100</p>	<p>Austria - Wels Tel: 43-7242-2244-39 Fax: 43-7242-2244-393</p> <p>Denmark - Copenhagen Tel: 45-4485-5910 Fax: 45-4485-2829</p> <p>Finland - Espoo Tel: 358-9-4520-820</p> <p>France - Paris Tel: 33-1-69-53-63-20 Fax: 33-1-69-30-90-79</p> <p>Germany - Garching Tel: 49-8931-9700</p> <p>Germany - Haan Tel: 49-2129-3766400</p> <p>Germany - Heilbronn Tel: 49-7131-72400</p> <p>Germany - Karlsruhe Tel: 49-721-625370</p> <p>Germany - Munich Tel: 49-89-627-144-0 Fax: 49-89-627-144-44</p> <p>Germany - Rosenheim Tel: 49-8031-354-560</p> <p>Israel - Ra'anana Tel: 972-9-744-7705</p> <p>Italy - Milan Tel: 39-0331-742611 Fax: 39-0331-466781</p> <p>Italy - Padova Tel: 39-049-7625286</p> <p>Netherlands - Druenen Tel: 31-416-690399 Fax: 31-416-690340</p> <p>Norway - Trondheim Tel: 47-72884388</p> <p>Poland - Warsaw Tel: 48-22-3325737</p> <p>Romania - Bucharest Tel: 40-21-407-87-50</p> <p>Spain - Madrid Tel: 34-91-708-08-90 Fax: 34-91-708-08-91</p> <p>Sweden - Gothenberg Tel: 46-31-704-60-40</p> <p>Sweden - Stockholm Tel: 46-8-5090-4654</p> <p>UK - Wokingham Tel: 44-118-921-5800 Fax: 44-118-921-5820</p>