



Product Change Notification - GBNG-06TAXU283

Date:

09 May 2018

Product Category:

Bluetooth Module; Wireless Modules

Affected CPNs:**Notification subject:**

CCB 2795 Final Notice: Qualification of FLCT as a new assembly site for RN41, RN42, RN42N and RN52 Bluetooth module products.

Notification text:**PCN Status:**

Final notification

PCN Type:

Manufacturing Change

Microchip Parts Affected:

Please open one of the icons found in the Affected CPNs section above.

NOTE: For your convenience Microchip includes identical files in two formats (.pdf and .xls).

Description of Change:

Qualification of FLCT as a new assembly site for RN41, RN42, RN42N and RN52 Bluetooth module products.

Pre Change:

Assembled at FCOT assembly site

Post Change:

Assembled at FLCT assembly site.

Pre and Post Change Summary:

	Pre Change	Post Change
Assembly Site	Flaircomm Technology, Inc. (FCOT)	Flaircomm Technology, Inc. (FLCT)
Factory Location	Shenzhen China	Fujian China

Impacts to Data Sheet:

None

Change Impact:

None

Reason for Change:

To improve productivity by qualifying FLCT as a new assembly site.

Change Implementation Status:

In Progress

Estimated First Ship Date:

June 09, 2018 (date code: 1823)

NOTE: Please be advised that after the estimated first ship date customers may receive pre and post change parts.

Time Table Summary:



Workweek	February					à	May 2018				June 2018				
	05	06	07	08	09		18	19	20	21	22	23	24	25	26
Initial PCN Issue Date			X												
Qualification Report Availability							X								
Final PCN Issue Date							X								
Estimated Implementation Date											X				

Method to Identify Change:

Traceability code

Qualification Report:

Please open the attachments included with this PCN labeled as PCN_#_Qual Report.

Revision History:

February 28, 2017: Issued initial notification.

May 09, 2018: Issued final notification. Attached the Qualification Report. Revised the affected parts list. Provided estimated first ship date on June 09, 2018.

The change described in this PCN does not alter Microchip’s current regulatory compliance regarding the material content of the applicable products.

Attachment(s):

[PCN_GBNG-06TAXU283_Qual Report.pdf](#)

Please contact your local [Microchip sales office](#) with questions or concerns regarding this notification.

Terms and Conditions:

If you wish to change your product/process change notification (PCN) profile please log on to our website at [microchip.com/PCN](#) sign into myMICROCHIP to open the myMICROCHIP home page, then select a profile option from the left navigation bar.

To opt out of future offer or information emails (other than product change notification emails), click here to go to [microchip DIRECT](#) and login, then click on the "My account" link, click on "Update profile" and un-check the box that states "Future offers or information about Microchip's products or services."

Affected Catalog Part Numbers (CPN)

RN41APL-I/RM
RN41APL-I/RM536
RN41APL-I/RM545
RN41APL-I/RM550
RN41APL-I/RMCF523
RN41HCI-I/RM
RN41HID-I/RM
RN41-I/RM
RN41-I/RM477
RN41-I/RM611
RN41-I/RM615
RN41-I/RM630
RN41-I/RMELAN477
RN41-I/RMEWR616
RN41-I/RMEWR617
RN41-I/RMF477
RN41-I/RMGPS100
RN41-I/RMVTR427
RN41NAPL-I/RM
RN41NAPL-I/RM543
RN41NAPL-I/RM545
RN41N-I/RM
RN41N-I/RM477
RN41N-I/RM615
RN41SM-I/RM
RN41U-I/RM
RN41XVC-I/RM
RN41XVU-I/RM
RN42APL-I/RM
RN42APL-I/RM536
RN42APL-I/RM543
RN42APL-I/RM545
RN42APL-I/RM550
RN42APL-I/RMFLY502
RN42HCI-I/RM
RN42HID-I/RM
RN42-I/RM
RN42-I/RM477
RN42-I/RM611
RN42-I/RM615
RN42-I/RM630
RN42-I/RMCOS477
RN42-I/RMETI540
RN42-I/RMEVO519
RN42-I/RMFLC014
RN42-I/RMFLC111
RN42-I/RMGPO100

RN42-I/RMPLX611
RN42-I/RMSQA477
RN42NAPL-I/RM
RN42NAPL-I/RM545
RN42NAPL-I/RMIWL537
RN42NHCI-I/RM
RN42NHID-I/RM
RN42N-I/RM
RN42N-I/RM477
RN42N-I/RMCOS477
RN42NU-I/RM
RN42SM-I/RM
RN42U-I/RM
RN42XVP-I/RM
RN42XVU-I/RM
RN52AAC-I/RM116
RN52ACV-I/RM116
RN52APC-I/RM116
RN52APC-I/RM117
RN52APT-I/RM116
RN52CVC-I/RM116
RN52-I/RM
RN52-I/RM110
RN52-I/RM116
RN52-I/RMEAS116
RN52SRC-I/RM100
RN52UDF-I/RM116