

Eaton Electronics Division 5735 W. Las Positas Blvd #100 Pleasanton, CA 94588 www.eaton.com/electronics

# **Product Change Notice**

PCN#: EE-PCN22016 August 12, 2022


### **CLASSIFICATION OF CHANGE:**

Packaging change.


### **DESCRIPTION OF CHANGE:**

Add a step to the tape and reel bottom cavity in order to create a tighter fit of the inductor within the cavity.

#### Old version:



#### New version:



## **REASON FOR CHANGE:**

Reducing the movement of the inductor within the cavity of the tape and reel prevents dropped inductors during pick and place process.

# **EXPECTED INFLUENCE ON QUALITY, RELIABILITY, AND PERFORMANCE:**

There will be no effect on the quality, reliability, or performance. There are no changes to form, fit, and function of the devices.

# PARTS FAMILIES AFFECTED:

FP1012V2-R070-R	FP1012V3-R070-R
FP1012V2-R080-R	FP1012V3-R080-R
FP1012V2-R090-R	FP1012V3-R090-R
FP1012V2-R100-R	FP1012V3-R100-R
FP1012V2-R120-R	FP1012V3-R120-R
FP1012V2-R150-R	FP1012V3-R150-R
FP1012V2-R330-R	FP1012V3-R240-R
FP1012V2-R470-R	FP1012V3-R330-R

### TIME SCHEDULE:

Start Shipment Date: Retroactive from March 1, 2022

Last Time Buy Date: N/A Last Time Shipment Date: N/A

# **SAMPLE AVAILABILITY:**

Available upon request

# **QUALIFICATION DATA:**

Available upon request

# **ISSUED BY:**

Global Product Manager: Steve Subiry

# **CONTACT INFORMATION:**

For questions or comments, please contact your local <u>Eaton sales representative</u>.