

<b>PCN Number:</b>	20180208000	<b>PCN Date:</b>	February 21, 2018
<b>Title:</b>	Datasheet for LM25141-Q1		
<b>Customer Contact:</b>	<a href="#">PCN Manager</a>	<b>Dept:</b>	Quality Services
<b>Change Type:</b>			
<input type="checkbox"/>	Assembly Site	<input type="checkbox"/>	Design
<input type="checkbox"/>	Assembly Process	<input checked="" type="checkbox"/>	Data Sheet
<input type="checkbox"/>	Assembly Materials	<input type="checkbox"/>	Part number change
<input type="checkbox"/>	Mechanical Specification	<input type="checkbox"/>	Test Site
<input type="checkbox"/>	Packing/Shipping/Labeling	<input type="checkbox"/>	Test Process
		<input type="checkbox"/>	Wafer Bump Site
		<input type="checkbox"/>	Wafer Bump Material
		<input type="checkbox"/>	Wafer Bump Process
		<input type="checkbox"/>	Wafer Fab Site
		<input type="checkbox"/>	Wafer Fab Materials
		<input type="checkbox"/>	Wafer Fab Process

### Notification Details

#### Description of Change:

Texas Instruments Incorporated is announcing an information only notification. The product datasheet(s) is being updated as summarized below. The following change history provides further details.



LM25141-Q1

SNVSAP9A | MARCH 2017 – REVISED FEBRUARY 2018

#### Changes from Original (March 2017) to Revision A

Page

• Added top navigator icon for TI Design reference design .....	1
• Changed EVM MOSFET part number from: "CDS18534Q5A" to: "CSD18534Q5A" .....	29
• Changed "+" to "x" in Equation 55 .....	33

The datasheet number will be changing.

Device Family	Change From:	Change To:
LM25141-Q1	SNVSAP9	SNVSAP9A

These changes may be reviewed at the datasheet links provided.

<http://www.ti.com/product/LM25141-Q1>

#### Reason for Change:

To accurately reflect device characteristics.

#### Anticipated impact on Fit, Form, Function, Quality or Reliability (positive / negative):

No anticipated impact. This is a specification change announcement only. There are no changes to the actual device.

#### Changes to product identification resulting from this PCN:

None.

#### Product Affected:

LM25141QRGERQ1	LM25141QRGETQ1		
----------------	----------------	--	--

For questions regarding this notice, e-mails can be sent to the regional contacts shown below or your local Field Sales Representative.

Location	E-Mail
USA	<a href="mailto:PCNAmericasContact@list.ti.com">PCNAmericasContact@list.ti.com</a>
Europe	<a href="mailto:PCNEuropeContact@list.ti.com">PCNEuropeContact@list.ti.com</a>
Asia Pacific	<a href="mailto:PCNAsiaContact@list.ti.com">PCNAsiaContact@list.ti.com</a>
Japan	<a href="mailto:PCNJapanContact@list.ti.com">PCNJapanContact@list.ti.com</a>