

Product Change Notice

Issue Date: 25 Jan 2018**Change Type:**

Device marking or labelling method

Parts Affected:

4N25	4N35	CNY17-1	CNY17-2	CNY17-3
CNY17-4	ACPL-827	ACPL-847	ACPL-824	ACPL-844

All associated options will also be affected. See Appendix for full part number list.

Description and Extent of Change:

Change to laser marking on 300mil DIP6, 300mil DIP8 and 300mil DIP16.

Reasons for Change:

Process standardization for better marking quality.

Effect of Change on Fit, Form, Function, Quality, or Reliability:

There is no change in fit, form, function, quality and reliability.

Effective Date of Change:

Products shipments using this change will begin with datecode starting from 1809.

Qualification Data:

Not applicable. This change had no impact to product reliability.

These changes have been reviewed and approved by Broadcom Limited engineers and managers per Broadcom Limited procedure: Change Control and Customer Notification, 5962-6052-80.

Please contact your Broadcom Limited field sales for any questions or support requirements. Please return any response as soon as possible, but not to exceed 30 days.

Appendix:

Affected Part Number
ACPL-824-W00E
ACPL-824-W60E
ACPL-824-300E

ACPL-824-000E
ACPL-824-360E
ACPL-824-500E
ACPL-824-060E
ACPL-824-560E
ACPL-847-W00E
ACPL-847-060E
ACPL-847-000E
ACPL-847-W60E
ACPL-847-360E
ACPL-847-300E
ACPL-827-W0BE
ACPL-827-00BE
ACPL-827-W6BE
ACPL-827-36BE
ACPL-827-50BE
ACPL-827-56BE
ACPL-827-06BE
ACPL-827-30BE
ACPL-827-W60E
ACPL-827-300E
ACPL-827-560E
ACPL-827-500E
ACPL-827-360E
ACPL-827-000E
ACPL-827-060E
ACPL-827-W00E
ACPL-827-W6CE
ACPL-827-00CE
ACPL-827-30CE
ACPL-827-50CE
ACPL-827-56CE
ACPL-827-06CE
ACPL-827-W0CE
ACPL-827-36CE
ACPL-847-06GE

ACPL-847-00GE
ACPL-847-W0GE
ACPL-847-W6GE
ACPL-847-36GE
ACPL-847-30GE
ACPL-844-060E
ACPL-844-000E
ACPL-844-W60E
ACPL-844-W00E
ACPL-844-300E
ACPL-844-360E
4N35-300E
4N25-000E
CNY17-3-000E
CNY17-1-300E
CNY17-1-500E
CNY17-2-000E
CNY17-3-500E
CNY17-2-500E
CNY17-3-060E
CNY17-3-300E
CNY17-3-360E
CNY17-1-W00E
CNY17-1-060E
CNY17-1-W60E
4N25-W00E
4N25-300E
4N25-500E
4N25-060E
4N25-W60E
4N25-360E
4N25-560E
4N35-000E
4N35-W00E
4N35-500E
4N35-060E

4N35-W60E
CNY17-3-560E
CNY17-3-W00E
CNY17-4-000E
CNY17-4-060E
CNY17-4-300E
CNY17-4-360E
CNY17-4-500E
4N35-360E
4N35-560E
CNY17-1-000E
CNY17-1-360E
CNY17-1-560E
CNY17-2-W00E
CNY17-2-300E
CNY17-2-060E
CNY17-2-W60E
CNY17-2-360E
CNY17-2-560E
CNY17-3-W60E
CNY17-4-W00E
CNY17-4-W60E
CNY17-4-560E

Affected Part Numbers

4N25-000E	ACPL-827-00BE	ACPL-844-300E	CNY17-2-060E
4N25-060E	ACPL-827-00CE	ACPL-844-360E	CNY17-2-300E
4N25-300E	ACPL-827-060E	ACPL-844-W00E	CNY17-2-360E
4N25-360E	ACPL-827-06BE	ACPL-844-W60E	CNY17-2-500E
4N25-500E	ACPL-827-06CE	ACPL-847-000E	CNY17-2-560E
4N25-560E	ACPL-827-300E	ACPL-847-00GE	CNY17-2-W00E
4N25-W00E	ACPL-827-30BE	ACPL-847-060E	CNY17-2-W60E
4N25-W60E	ACPL-827-30CE	ACPL-847-06GE	CNY17-3-000E
4N35-000E	ACPL-827-360E	ACPL-847-300E	CNY17-3-060E
4N35-060E	ACPL-827-36BE	ACPL-847-30GE	CNY17-3-300E
4N35-300E	ACPL-827-36CE	ACPL-847-360E	CNY17-3-360E
4N35-360E	ACPL-827-500E	ACPL-847-36GE	CNY17-3-500E
4N35-500E	ACPL-827-50BE	ACPL-847-W00E	CNY17-3-560E
4N35-560E	ACPL-827-50CE	ACPL-847-W0GE	CNY17-3-W00E
4N35-W00E	ACPL-827-560E	ACPL-847-W60E	CNY17-3-W60E
4N35-W60E	ACPL-827-56BE	ACPL-847-W6GE	CNY17-4-000E
ACPL-824-000E	ACPL-827-56CE	CNY17-1-000E	CNY17-4-060E
ACPL-824-060E	ACPL-827-W00E	CNY17-1-060E	CNY17-4-300E
ACPL-824-300E	ACPL-827-W0BE	CNY17-1-300E	CNY17-4-360E
ACPL-824-360E	ACPL-827-W0CE	CNY17-1-360E	CNY17-4-500E
ACPL-824-500E	ACPL-827-W60E	CNY17-1-500E	CNY17-4-560E
ACPL-824-560E	ACPL-827-W6BE	CNY17-1-560E	CNY17-4-W00E
ACPL-824-W00E	ACPL-827-W6CE	CNY17-1-W00E	CNY17-4-W60E
ACPL-824-W60E	ACPL-844-000E	CNY17-1-W60E	
ACPL-827-000E	ACPL-844-060E	CNY17-2-000E	