



Product Change Notification - SYST-14HZAE373

Date: 15 Jun 2017
Product Category: USB to Ethernet Controllers
Affected CPNs:  
Notification subject: Data Sheet - LAN7800 - SuperSpeed USB 3.1 Gen 1 10/100/1000 Ethernet Controller Data Sheet Document Revision
Notification text: SYST-14HZAE373

Microchip has released a new DeviceDoc for the LAN7800 - SuperSpeed USB 3.1 Gen 1 10/100/1000 Ethernet Controller of devices. If you are using one of these devices please read the document located at [LAN7800 - SuperSpeed USB 3.1 Gen 1 10/100/1000 Ethernet Controller](#).

Notification Status: Final

Description of Change: 1) Removed +2.5V from Switcher Input Voltage description for Table 3-2, Pin Assignments 2) Changed +2.5-3.3V to +3.3V in Figure 4-1, Power Connection Diagram 3) Added package thermal information for the 6x6mm 48-pin SQFN package in Section 16.3, Package Thermal Specifications.

Impacts to Data Sheet: None

Reason for Change: To Improve Manufacturability

Change Implementation Status: Complete

Date Document Changes Effective: 15 June 2017

NOTE: Please be advised that this is a change to the document only the product has not been changed.

Markings to Distinguish Revised from Unrevised Devices: N/A

Attachment(s): [LAN7800 - SuperSpeed USB 3.1 Gen 1 10/100/1000 Ethernet Controller](#)

Please contact your local [Microchip sales office](#) with questions or concerns regarding this notification.

Terms and Conditions:

If you wish to change your product/process change notification (PCN) profile please log on to our website at <http://www.microchip.com/PCN> sign into myMICROCHIP to open the myMICROCHIP home page, then select a profile option from the left navigation bar.

To opt out of future offer or information emails (other than product change notification emails), click here to go to [microchipDIRECT](#) and login, then click on the "My account" link, click on "Update profile" and un-check the box that states "Future offers or information about Microchip's products or services."

Affected Catalog Part Numbers (CPN)

LAN7800-V/VSX
LAN7800T-V/VSX
LAN7800T-I/Y9X
LAN7800T-I/VSXVAO
LAN7800T-I/VSX
LAN7800T/Y9X
LAN7800T/VSX
LAN7800-I/Y9X
LAN7800-I/VSXVAO
LAN7800-I/VSX
LAN7800/Y9X
LAN7800/VSX