



CUSTOMER OPERATIONS
160 RIO ROBLES
SAN JOSE, CA 95134

PDN #: M000877

DATE: 09-Nov-2018

PRODUCT DISCONTINUANCE NOTICE

Notice Type	Maxim Part Number	Recommended Replacement	Last Order Date	Last Delivery Date	Reason
Reactivation	MAXQ1851-BNS+	N/A			Part reactivated from prior notice: M000864
Discontinuance	DS28CM00EVKIT	N/A	09-Nov-2018	09-Nov-2018	EVKIT is No Longer Supported
Discontinuance	DS28CN01EVKIT	N/A	09-Nov-2018	09-Nov-2018	EVKIT is No Longer Supported
Discontinuance	DS28E01PMOD+	N/A	09-Nov-2018	09-Nov-2018	EVKIT is No Longer Supported
Discontinuance	DS28EL35QA-742+2T	DS28E35Q+T	09-Nov-2018	09-Nov-2018	Part can no longer be manufactured
Discontinuance	DS3922EVKIT#	N/A	09-Nov-2018	09-Nov-2018	EVKIT is No Longer Supported
Discontinuance	MAX17250EVKIT#	MAX17250EVKIT#WLP	09-Nov-2018	09-Nov-2018	EVKIT is No Longer Supported
Discontinuance	MAX17621ATA+	N/A	09-Nov-2019	10-May-2020	The part was not released
Discontinuance	MAX20092EVKIT#	MAX20092EVSYS#	09-Nov-2018	09-Nov-2018	EVKIT is No Longer Supported
Discontinuance	MAX32660-EVKIT#	MAX32660-EVSYS#	09-Nov-2018	09-Nov-2018	EVKIT is No Longer Supported
Discontinuance	MAX36051EVKIT#	N/A	09-Nov-2018	09-Nov-2018	EVKIT is No Longer Supported
Discontinuance	MAX8831EWE+	N/A	09-Nov-2019	10-May-2020	Part can no longer be manufactured
Discontinuance	MAXQ61HX-2047+	N/A	09-Nov-2019	10-May-2020	Part can no longer be manufactured
Discontinuance	MAXQ61HX-2594+	N/A	09-Nov-2019	10-May-2020	Part can no longer be manufactured
Discontinuance	MAXQ61HX-2597+	N/A	09-Nov-2019	10-May-2020	Part can no longer be manufactured
Discontinuance	MAXQ61HX-2620+	N/A	09-Nov-2019	10-May-2020	Part can no longer be manufactured
Discontinuance	MAXQ61HX-2621+	N/A	09-Nov-2019	10-May-2020	Part can no longer be manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 10-Dec-2018